

KD a OcU Zahorce

mist/i	tepl	nj.	nazev	vykon	rmatura	DNarm	nast.	Pa	DNp
<hr/>									
STUPACKA	1								
112/ 1	20°	6	- P 90 600/11K	Q= 440 W	P VExakt D /2	15	.09/	7034	15
STUPACKA	3								
110/ 1	20°	8	- P 90 600/22K	Q= 970 W	P VExakt D /4	15	.20/	7470	15
STUPACKA	4								
107/ 1	20°	6	- P 90 600/11K	Q= 440 W	P VExakt D /2	15	.10/	6971	15
108/ 1	20°	10	- P 90 600/21K	Q= 1050 W	P VExakt D /4	15	.23/	6937	15
STUPACKA	5								
106/ 2	20°	12	- P 90 600/22K	Q= 1330 W	P VExakt D /5	15	.31/	6181	15
STUPACKA	6								
106/ 1	20°	12	- P 90 600/22K	Q= 1330 W	P VExakt D /5	15	.32/	5646	15
105/ 1	10°	10	- P 90 600/21K	Q= 1410 W	P VExakt D /5	15	.34/	5619	15
STUPACKA	7								
104/ 1	20°	8	- P 90 600/22K	Q= 970 W	P VExakt D /5	15	.25/	5039	15
101/ 1	20°	6	- P 90 600/21K	Q= 630 W	P VExakt D /3	15	.16/	5054	15
STUPACKA	8								
102/ 1	20°	6	- P 90 600/21K	Q= 630 W	P VExakt D /4	15	.19/	3764	15
STUPACKA	9								
102/ 2	20°	12	- P 90 600/22K	Q= 1460 W	P VExakt D /6	15	.47/	3215	15
STUPACKA	10								
213/ 1	20°	12	- P 90 600/22K	Q= 1330 W	P VExakt D /6	15	.43/	3263	15
STUPACKA	2								
111/ 1	20°	11	- P 90 600/22K	Q= 1330 W	P VExakt D /5	15	.30/	6670	15
111/ 2	20°	11	- P 90 600/22K	Q= 1330 W	P VExakt D /5	15	.30/	6670	15
STUPACKA	15								
211/ 1	20°	10	- P 90 600/21K	Q= 1210 W	P VExakt D /6	15	.37/	3558	15
STUPACKA	11								
204/ 1	20°	10	- P 90 600/22K	Q= 1210 W	P VExakt D /6	15	.42/	2728	15
203/ 1	20°	8	- P 90 900/22K	Q= 1210 W	P VExakt D /6	15	.42/	2728	15
STUPACKA	21								
203/ 4	20°	12	- P 90 600/22K	Q= 1210 W	P VExakt D /6	15	.47/	2231	15
204/ 2	20°	10	- P 90 600/22K	Q= 1210 W	P VExakt D /6	15	.47/	2231	15
STUPACKA	17								
302/ 1	20°	8	- P 90 600/21K	Q= 840 W	P VExakt D /4	15	.22/	4880	15
STUPACKA	14								
209/ 3	20°	9	- P 90 600/21K	Q= 840 W	P VExakt D /4	15	.23/	4339	15
STUPACKA	16								
209/ 1	20°	9	- P 90 600/21K	Q= 840 W	P VExakt D /5	15	.25/	3623	15
209/ 2	20°	9	- P 90 600/21K	Q= 840 W	P VExakt D /5	15	.25/	3623	15
STUPACKA	13								
202/ 1	20°	9	- P 90 600/21K	Q= 840 W	P VExakt D /5	15	.24/	4177	15
STUPACKA	12								
203/ 2	20°	12	- P 90 600/22K	Q= 1210 W	P VExakt D /6	15	.37/	3474	15
203/ 3	20°	12	- P 90 600/22K	Q= 1210 W	P VExakt D /6	15	.37/	3474	15
STUPACKA	18								
206/ 1	20°	6	- P 90 600/11K	Q= 440 W	P VExakt D /3	15	.12/	4228	15
STUPACKA	19								
202/ 2	20°	9	- P 90 600/21K	Q= 840 W	P VExakt D /5	15	.25/	3702	15
STUPACKA	20								
203/ 5	20°	12	- P 90 600/22K	Q= 1210 W	P VExakt D /6	15	.40/	2999	15
203/ 6	20°	12	- P 90 600/22K	Q= 1210 W	P VExakt D /6	15	.40/	2999	15